



## **Seymour, Oxford and Becan Falls-Valley System 2011 Lead Compliance Testing Results**

### System is in Compliance

1	06/30/2011	None Detected
2	06/30/2011	None Detected
3	06/30/2011	None Detected
4	06/30/2011	None Detected
5	06/30/2011	None Detected
6	06/30/2011	None Detected
7	06/30/2011	None Detected
8	06/30/2011	None Detected
9	06/30/2011	None Detected
10	06/30/2011	None Detected
11	06/30/2011	None Detected
12	06/30/2011	None Detected
13	06/30/2011	None Detected
14	06/30/2011	None Detected
15	06/30/2011	None Detected
16	06/30/2011	None Detected
17	06/30/2011	None Detected
18	06/30/2011	None Detected
19	06/30/2011	None Detected
20	06/30/2011	None Detected
21	06/30/2011	None Detected
22	06/30/2011	None Detected
23	06/30/2011	None Detected
24	06/30/2011	None Detected
25	06/30/2011	None Detected
26	06/30/2011	1
27	06/30/2011	1
28	06/30/2011	1
29	06/30/2011	2
30	06/30/2011	3
31	06/30/2011	3
32	06/30/2011	79

**PWS ID#: CT1240011**