



**Seymour, Oxford and Becan Falls- Valley System**  
**2014 Lead Compliance Testing Results**  
**System is in Compliance**

<b>Rank</b>	<b>Collection Date</b>	<b>Lead Results (ppb)</b>
1	07/10/2014	None Detected
2	07/10/2014	None Detected
3	07/10/2014	None Detected
4	07/10/2014	None Detected
5	07/10/2014	None Detected
6	07/10/2014	None Detected
7	07/10/2014	None Detected
8	07/10/2014	None Detected
9	07/10/2014	None Detected
10	07/10/2014	None Detected
11	07/10/2014	None Detected
12	07/10/2014	None Detected
13	07/10/2014	None Detected
14	07/10/2014	None Detected
15	07/10/2014	None Detected
16	07/10/2014	None Detected
17	07/10/2014	None Detected
18	07/10/2014	None Detected
19	07/10/2014	None Detected
20	07/10/2014	None Detected
21	07/10/2014	None Detected
22	07/10/2014	1
23	07/10/2014	1
24	07/10/2014	1
25	07/10/2014	2
26	07/10/2014	2
27	07/10/2014	3
28	07/10/2014	3
29	07/10/2014	3
30	07/10/2014	4
31	07/10/2014	7
32	07/10/2014	12

**PWS ID#: CT1240011**